

should be etched with muriatic acid and primed with Wearcoat 490.

All surfaces should be free of scaling rust, grease, oil, dirt, or other contaminants.

Application

Thoroughly mix each component, then combine components and mechanically mix.

Allow to stand for approximately 1 hour to start initial chemical reaction before using.

Apply by brush, roller, or spray. Do not apply when the temperature of the substrate is below 50°F.

Precautions

Contains aromatic hydrocarbons and glycol ethers. **HARMFUL OR FATAL IF**

SWALLOWED. COMBUSTIBLE.

Vapor Harmful, Eye Irritant. If

swallowed, do not induce vomiting. Call physician immediately. Avoid prolonged contact with skin, do not breathe vapor or spray mist. In case of contact with eyes, flush repeatedly with water and contact physician.

Keep away from heat, sparks and open flames. Prohibit smoking. Use explosion proof equipment. Use with adequate ventilation. In confined areas, use adequate forced ventilation during application and drying. In areas where there is a minimum of air movement, a fresh air mask (such as #W-92 manufactured by 3M Co.) should be used.

Refer also to Material Safety Data Sheet.

FOR INDUSTRIAL USE ONLY.

The information presented herein while not guaranteed, is to the best of our knowledge true and correct. No warranty or guarantee, express or implied is made regarding performance of any product since the manner of use and application is beyond our control.

BULLETIN 491.1

11/92